

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

Minerals Inspection Report

Report Date: 09/04/2013

Reviewed M

Mine Name: Hical 1	Permit Number:	M/023/0071	Mine Status:	Reclaimed	7		
Operator Name: Triumph Mining Corporation	Inspection Date:	08/30/2013	Permit Fees:	No Fee Req.			
Inspector(s): Wayne Western	Inspection Time:	10:20 - 10:45	Bond Amount:	\$6,000			
Attendee(s):	Weather:	80's fair skies	Bond Escalation:	10/13/2005	Carl Contract		
Inspection Purpose: Routine inspection			Prior Inspection:	06/24/2010	4		

Conclusions and Recommendations

	Elements of Inspection	Evaluated & Commented	Enforcement	
1.	Permits, Revisions, Transfer, Bonds			
	The bond on the site is adequate because on only remaining requirement is 7	0% cover		
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages/Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)			
8.	Soils			
9.	Revegetation			
	The vegetation on the site does not appear to meet 70% of surrounding cover	The Operator might want to consider rese	eding this fall.	
10.				

Inspector's Signature: Way Wallers

CC: Duane Bays RIM

CC: Duane Bays, BLM

File: /O/M023-Juab/M0230071-HiCal/inspections/Insp08302013.pdf




Mine: Inspected: 08/30/2013





Reclaimed area Reclaimed area







Plants

